



Micro-Color lithography

W. A. KRUEGER CO. (INCORPORATED)

ROBERT D. BALL  
VICE PRESIDENT/SALES  
EASTERN SALES

August 30, 1973

Mr. A. R. D'Agostino  
Deansboro  
New York

Dear Nemo:

My golf course committee is disturbed that very little repair work has been accomplished since our meeting with Tom Fazio on July 17. We realize some work should have been delayed until now, but it is reported to us by Larry that you have not given any indication of a date you plan to begin. And you will recall that a great amount of rock raking was to be done very soon after July 17, but none was. Nor was the intake for the pump lowered to at least 10 feet.

We have also encountered numerous problems with the pumping station and the exposed pipe near the second tee has broken. The aluminum line connecting the pump to the lake is not satisfactory and we want it replaced. It has cracked on many occasions and has to be patched. Another fault is that the pump does not hold its prime thus requiring two people to get it operating. We think that should be corrected.

Many of the items discussed for repair were, of course, minor and not requiring immediate attention. But since the other items were not completed as promised, and since you have not given Larry any date for beginning, the committee requested I write with regard to these items. The committee also requests the areas requiring new seed be completed immediately. In discussing this with Tom, he said it should be done next week, September 3-10. We agree.

We would appreciate your cooperation.

Sincerely,

Don Brooks  
Chairman, Dlh-y-Ridge  
Golf Course Committee

DB/rch

CC: Mr. Tom Fazio  
Mr. Joe McLinden  
Committee Members